



# WL Transmitters

We inform you that following the obsolescence of a component, we have been forced to **update** the electronic boards that make up our transmitters of the WireLess range.

The new components do not guarantee **backward compatibility**. Therefore, once the stocks of transmitters are exhausted, in case of loss or breakage of the transmitter, in the presence of the old series of WL remote controls, it will be necessary to replace transmitter and receiver.

**It is possible to immediately recognise the old version from the new one, thanks to the color change adopted on the label:**

Old version	New version (2 series)
<p><b>10105141416</b> TX RICETRASM 6CH  <b>10105141356</b> TX RICETRASM WL 2CH</p>	<p><b>10105141630</b> TX RICETRASM WL 6CH 2°SERIE  <b>10105141649</b> TX RICETRASM WL 2CH 2°SERIE</p>
 <p>The label for the old version transmitter is black with a vertical 'MADE IN ITALY' strip on the left. It features the '2WL Transceiver' logo in red and white, and the 'OMFB' logo in white. Below the logos, it says '2WL RX'. There are two circular logos: a CE mark and an 'E24' mark. To the right, there are two boxes containing 'e24' and '03 1862' in the top row, and '10R' and '03 0578' in the bottom row. At the bottom, it lists 'O.M.F.B. S.p.A. Hydraulic Components', 'Provaglio d'Iseo - Via Cave, 7/9 25050 (BS) - Italy', and 'Tel. +39 030 98.30.611 - www.omfb.com'.</p>	 <p>The label for the new version transmitter is black with a vertical 'MADE IN ITALY' strip on the left. It features the '2WL Transceiver' logo in green and white, and the 'OMFB' logo in white. Below the logos, it says '2WL RX'. There are two circular logos: a CE mark and an 'E24' mark. To the right, there are two boxes containing 'e24' and '10R' in the top row, and two empty boxes in the bottom row. At the bottom, it lists 'O.M.F.B. S.p.A. Hydraulic Components', 'Provaglio d'Iseo - Via Cave, 7/9 25050 (BS) - Italy', and 'Tel. +39 030 98.30.611 - www.omfb.com'.</p>