

Refresh mounting kit

With a view to a constant improvement of the quality of our products and their adaptation to the technical equipment of the current ranges of industrial vehicles, we inform you that the fixing kits for tanks of the BI, BP, BQ, BR and BT ranges have been updated through the adoption of new stainless steel band/straps that guarantee a better coupling with the tank as well as a clear improvement in resistance performance in the field. Below you will find all the details.

WAS	BECOMES
<p>Asymmetrical fold</p> <p>Long flap</p> <p>Sharp edges</p>	<p>Diameter reduction to improve pin coupling and reduce material injury</p> <p>Symmetrical fold to reduce tension of the material</p> <p>Shorter flap</p> <p>Welding points closer</p> <p>Radiated terminal</p>
<p>Sash</p> <p>Rubber Sheath not mounted</p>	<p>Sash</p> <p>Rubber Sheath mounted</p>

The assembly kit codes remain unchanged as indicated in the catalogue.

However, these changes have made it necessary to create new spare parts codes as indicated in the table below:

Type	Current range	New band/strap code+rubber sheath	Rubber Sheath
BI	538200BI1X1	135990BI1X0	50620001004
BL	538200BL1X2	135990BL1X0	50620001008
BP	538200BP1X2	135990BP1X0	50620001003
BQ	538200BL1X2	135990BQ1X0	50620001001
BR	538200BR1X1	135990BR1X0	50620001002
BT	538200BT1X1	135990BT1X0	50620001006

The old codes are placed at the end of the series until the stocks are completely exhausted. The transition times will therefore vary depending on the model.